

Plastic Welding

Part 3: Fundamental Principals of Welding



We know how.

Definition

Plastic welding according to German Industrial Norm (DIN)1910, Part 3 is the joining of thermoplastics using heat and pressure.


The fusion surfaces must be in the thermoplastic condition. A filler material may or may not be added

Three important welding parameters

- Temperature
- Pressure
- Time



Welding Discharge





Basics

High quality of the weld depends on the following aspects:

- Material and welding rod properties (e.g.flame-retardant)
- The welding method
- The quality of the welding equipment and machines
- Take care on the parameters of the welding method
- The ambient influences
- The construction of the container/apparatus/pipeline
- The preparing of the form of joint (opening angle, x-joint)
- The knowledge and responsibility of the welder



Welding of Plastics

As a rule only the same thermoplastics are weldable with each other.

Due to their extremely high molecular weight some thermoplastics don't attain sufficient flowability. Such thermoplastics have limited weldability.

- e.g. ultra high molecular PE-HD (UHMW)
 - cast PMMA
 - PTFE



Influences of Material Properties

Material	Thermal conductivity λ =W/mK	Coefficient of linear thermal expansion α=mm/mK	Example 100m Pipe Δ 20°C [cm]
Steel	52	0.011	2.36
Copper	372	0.016	3.3
PVC	0.15	0.08	16
PE-HD	0.41	0.20	40
PP	0.23	0.15	30
PVDF	0.14	0.13	26







Influences of Material Properties

- High thermal expansion results in great shrinkage during cooling, this leads to stress.
- Sufficient heating up of the welding surface must take place slowly.
- If heating of the welding area is performed to quickly, the material suffers thermal damage because plastics have a very poor heat conductivity.



Influence of the Welding Parameters

- Low-stress welded joints are produced if the following
- measures are adhered to:
- Steady heating of the welding zone
- Constant welding speed
- Constant welding pressure
- Heating of the welding zone to a sufficient depth
- Slow and even cooling. Shrinkage must not be impeded




Tuning of the Welding Parameters (1)

Low welding temperature and longer period of exposure results in



- •plastification of a big material volume
- Iow residual welding stress
- slow temperature drop





Tuning of the Welding Parameters (2)


Higher welding temperature and a shorter period of exposure results in:



•plastification of a small material volume

high residual welding stress

steep temperature rise





Influences During Welding

(DVS 2207)

- Ambient temperature (>5°C, 41°F)
- Wind, draft
- Air humidity
- Rain
- Sunshine





Welding Processes used in Plastic Fabrication

Hot Gas Free Hand welding (WF) or Fan welding

Hot Gas draw welding (WZ) or speed welding

Hot Gas Overlap welding (WU)

Hot Gas Extrusion welding (WE)











Welding Processes used in Plastic Fabrication

Heated plate welding (Butt welding) HS


Welding by bending and edging HB

Sleeve welding with spigot and Sleeve HD


Electro fusion welding (Coil welding) HM














Welding by Bending using a Heated Tool (HB)



S= material thickness



Sleeve Welding with Spigot and Sleeve (HD)

