ANSYS WB - Bike Crank - Solution

Author: Benjamin Mullen, Cornell University

Problem Specification

- 1. Pre-Analysis & Start-Up
- 2. Geometry
- 3. Mesh
- 4. Setup (Physics)
- 5. Solution
- 6. Results
- 7. Verification & Validation

Solution

Deformation

Although we are only looking for the strain at the strain gauge location, we should also check the deformation of the crank to see if the solution makes intuitive sense. This will allow us to catch any obvious errors we have made setting up the simulation. To add deformation to the solution, first click

Solution (B5) to add the solution sub menu to menu bar. Now in the solution sub menu click **Deformation > Total** to add the total deformation to the solution. It should appear in the outline tree.

Stress

We will also look at the stress of the bar to verify the simulation against the theory. In the solution sub menu, select *Stress > Normal*. In the details pane, ensure *Orientation* is set to *X Axis*, and *Geometry* is set to *All Bodies*. Rename the Stress to **StressXX**. Now, create another stress the same way, but change *Orientation* to *Y Axis* and rename it **StressYY**

Construction Geometry

The next thing we are going to do is to set up a path where the strain gauge lies on the bike crank. In the outline window, click Construction Geometry > Path. This will open up the path toolbox in the details window. Creating a path in Workbench is very easy: you just have to specify the starting and ending points of your path and workbench will create it. In the details window, enter (3.3748, -.20512, 0.375) as the starting point and (3.3748, 0.016929, 0.375) as the end point. Change the number of sampling points to 50.

Details of "Path"			
⊟	Definition		
	Path Type	Two Points	
	Path Coordinate System	Global Coordinate System	
	Number of Sampling Points	50.	
	Suppressed	No	
	Show Mesh	No	
▣	Start		
	Coordinate System	Global Coordinate System	
	Start X Coordinate	3.3748 in	
	Start Y Coordinate	-0.2051 in	
	Start Z Coordinate	0.375 in	
	Location	Click to Change	
▣	End		
	Coordinate System	Global Coordinate System	
	End X Coordinate	3.3748 in	
	End Y Coordinate	1.69e-002 in	
	End Z Coordinate	0.375 in	
	Location	Click to Change	

When the parameters of the path have been set, right click on the path you just created in the project tree in the outline window and select *Rename*. Rename the path, **Strain Gauge**.

If your default coordinate system is not centered on one of the holes in the crank, or you wish to learn how to define new coordinate systems inside the mechanical window, please refer to the following video:



Why Are We Creating a Path to Represent the Strain Gauge?

We are trying to find the average of the strain over the entire area of the strain gauge. However, lucky for us, the strain does not vary much in the x-direction of the bike crank. Therefore, we can neglect the strain changes in the x-direction, and assume strain only varies in the y-direction. This allows us to use a line as a representation of the strain gauge, making our analysis simpler and not harming our results.

An alternate, more difficult, and more accurate method than using paths is to use surface bodies to average the strain over the entire area covered by the strain gauge. The video below walks you through this process.

Strain

In the Solution sub menu select *Strain > Normal*. Now, we need to specify that we want the strain to be measured at the stain gauge in the y direction. To accomplish this, go to *Scoping Method > Path*, the select *Path > Strain Gauge* in the details window. To change the direction of the strain, select *Orienta tion > Y Axis*. The rest of the default options should suffice for our simulation.

Details of "Normal Elastic Strain"			
⊟	Scope		
	Scoping Method	Path	
	Path	Strain Gauge	
	Geometry	All Bodies	
▣	- Definition		
	Туре	Normal Elastic Strain	
	Orientation	Y Axis	
	Ву	Time	
	Display Time	Last	
	Coordinate System	Global Coordinate System	
	Calculate Time History	Yes	
⊫	Integration Point Results		
	Display Option	Averaged	
⊫	Results		
	Minimum	-4.9324e-005 in/in	
	Maximum	1.3965e-004 in/in	
⊫	Graph Controls		
	X-Axis	S	
+	± Information		

We are ready to solve the simulation. Press



Continue to Step 6: Results Go to all ANSYS Learning Modules See and rate the complete Learning Module