ANSYS 12 - LaminatePlate - Geometry

⚠ This Tutorial is Under Construction!

Author: John Singleton, Cornell University

2. Geometry

Launch Design Modeler

In order to start the Design Modeler *(Double Click) Geometry*. After the Design Modeler opens, select meter as the desired length unit.

Proper Orientation

The sketching will be done in the XY plane, so *(Click) XY Plane*, then click on the face plane button, .

Line Sketching

The laminate plate will be modeled using shell elements, thus the geometry needed will simply be a square in the XY Plane. In order to draw the rectangle *(Click) Sketching > (Click) Rectangle* then draw a rectangle in the XY Plane.

Dimensioning

Dimension the rectangle such that both sides are defined to be 10m.

Surface Creation

Here, the rectangle will be turned into a surface. To do so *(Click)Concept > Surface From Sketches*. Next, highlight all four edges of the rectangle and select *Apply* in the "Details of SurfaceSK1" table. Now, click the generate button, , in order to create the surface.

Go to Step 3: Mesh

See and rate the complete Learning Module

Go to all ANSYS Learning Modules