## **ANSYS WB - Plate With a Crack - Problem Specification**

Author: Benjamin Mullen, Cornell University

Problem Specification

- 1. Pre-Analysis & Start-Up
- 2. Geometry
- 3. Mesh
- 4. Setup (Physics)
- 5. Solution
- 6. Results
- 7. Verification & Validation

A plate with a center crack is subjected to a stress Unable to find DVI conversion log file.. The geometry is below. Determine the stress intenstiy factor KI.

Continue to Step 1 - Pre-Analysis and Startup