# **ANSYS - Semi-monocoque Shell**

- Problem Specification
- Step 1: Start-up and preliminary set-up
  - Create a folder
  - Start ANSYS
  - Set Preferences
  - Units
  - Enter Parameters
- Step 2: Specify element type and constants
  - Specify Element Type
    - Specify Element Constants
- Step 3: Specify material properties
- Step 4: Specify geometry •
  - Strategy for Geometry Creation
    - Keypoints Coordinates
  - Create Keypoints and Areas
- - Generate Mesh for Plate
  - Generate Mesh for Vertical Stiffener
  - Generate Mesh for Horizontal Stiffener
  - ° Copy Mesh in x-Direction
  - Copy Mesh in y-Direction
  - Copy Sub-Section ABCD
  - Merge Coincident Entities
  - Compress Item Numbers
- Step 6: Specify boundary conditions
  - Apply Symmetry along AH
  - Apply Symmetry along AJ
  - Apply Clamped BC along HI
     Apply Clamped BC along JI

  - Apply Pressure on Plate
  - Create Log File
- Step 7: Solve!
  - Step 8: Postprocess the results
    - Plot Deformed Shape
      - Plot w Displacement
      - Deflection at Facesheet Center
      - xx for Facesheet
      - yy for Facesheet
    - xx for Stiffeners
    - yy for Stiffeners
- Step 9: Validate the results
  - Comparison With Plate Theory

Author: Rajesh Bhaskaran, Cornell University

## **Problem Specification**

- 1. Start-up and preliminary set-up
- 2. Specify element type and constants
- 3. Specify material properties
- 4. Specify geometry
- 5. Mesh geometry
- 6. Specify boundary conditions
- 7. Solve!
- 8. Postprocess the results
- 9. Validate the results

## **Problem Specification**

In this tutorial, we'll analyze the plane shell with stiffeners shown in the figure below.



(Click for enlarged figure.)

All edges are clamped. A constant pressure of  $0.05 \text{ N/mm}^2$  acts on the underside of the shell (i.e. the pressure acts in the +z direction). Since the geometry and loads are symmetric about both the x and y-axes, we need to model only one-quarter of the structure. The dimensions of the plate and stiffeners are shown in the figure below which shows only one-quarter of the structure.



The Young's modulus  $E = 7.3 \times 10^4$  MPa and the Poisson ratio is 0.33. Print out this page and have it on hand so that you can easily refer to the geometry and problem specification as you go through the tutorial.

Go to Step 1: Start-up and preliminary set-up

See and rate the complete Learning Module

Go to all ANSYS Learning Modules

**Problem Specification** 

- 1. Start-up and preliminary set-up
- 2. Specify element type and constants
- 3. Specify material properties
- 4. Specify geometry
- 5. Mesh geometry
- 6. Specify boundary conditions
- 7. Solve!
- 8. Postprocess the results
- 9. Validate the results

## Step 1: Start-up and preliminary set-up

## Create a folder

Create a folder called shell at a convenient location. We'll use this folder to store files created during the session.

## Start ANSYS

On Windows systems, select the appropriate menu path. On my system, the path is

#### Start > Programs > ANSYS 10.0 > ANSYS Product Launcher

Enter the location of the folder shell that you just created as your Working directory by browsing to it.

Enter shell as your Initial jobname. Click on Run.

Resize windows as shown in this snapshot so that you can read instructions in your browser window and implement them in ANSYS.

#### **Set Preferences**

#### Main Menu > Preferences

In the *Preferences for GUI Filtering* dialog box, click on the box next to *Structural* so that a tick mark appears in the box. From now on, only the menu options valid for structural problems will be made available.

### Units

ANSYS leaves it to us to use a consistent set of units. For convenience, we'll use the following set of units: mm for geometric dimensions; N for forces; and N/mm<sup>2</sup> for Young's modulus and pressures. The resulting stresses will be in N/mm<sup>2</sup> or MPa. Convince yourself that this is a consistent unit system; don't take my word for it.

#### **Enter Parameters**

We'll play smart and create scalar parameters corresponding to the plate and stiffener dimensions\_.\_ This will later allow us to vary these parameters and perform optimization studies.

#### Utility Menu > Parameters > Scalar Parameters

#### Define a parameter for the plate length $I_1$ in mm:

L1=750

Click Accept. Similarly, define other parameters corresponding to the dimensions and click Accept after each (parameter names are not case-sensitive). Before you specify a parameter, refer to the geometry specification to remind yourself what dimension that parameter represents.

W1=250 W2=2 W3=2 H1=5 H2=15 H3=20

{{}}

We'll play smarter and also specify the number of stiffeners in each direction as parameters so that these too can be varied easily in tradeoff studies. We'll employ the labels NSX and NSY for the number of stiffeners in the x and y directions, respectively.

NSX=2 NSY=3

We'll use the above parameters when creating the geometry in Step 4. We'll also define some parameters which we'll use in Step 5 to set the mesh size along edges.

NDIV\_X=3 NDIV\_Y=6 SIZE\_Z=5

Close the Scalar Parameters window.

Go to Step 2: Specify Element Types and Constants

See and rate the complete Learning Module

Go to all ANSYS Learning Modules

- **Problem Specification**
- 1. Start-up and preliminary set-up
- 2. Specify element type and constants
- 3. Specify material properties
- 4. Specify geometry 5. Mesh geometry
- 6. Specify boundary conditions
- 7. Solve!
- 8. Postprocess the results
- 9. Validate the results

## Step 2: Specify element type and constants

Since thin structures can be modeled efficiently as shells, we'll use shell elements to build the finite-element model. Shell elements can support membrane and bending loads consistent with classical shell theory (sorry, FEA doesn't let you off from understanding basic theory). As you can imagine, shell elements are appropriate when the thickness of the structure is small compared to the other dimensions. The computational savings come about because only the mid-surface of the structure is modeled; the thickness and other cross-sectional properties are incorporated into the element stiffness matrix and input as "real constants" in ANSYS. (This is analogous to modeling beams using beam elements where the beams are modeled as lines with thickness and other cross-sectional properties being "real constants"). Section 2.10 in the ANSYS Element Reference manual gives you a page of useful information on shell elements. Be sure to peruse it in the online documentation since it'll be on the final. 😌

## Specify Element Type

Let's take a peek at the shell elements available in ANSYS. Bring up the ANSYS documentation window, select the Search tab, enter the phrase "pictorial summary" and click on List Topics. Then double-click on 3.2 Pictorial Summary in the left pane. At the top of the pictorial summary of element types in the right pane, click on SHELL Elements. This brings up the list of shell elements available in ANSYS including many with specialized capabilities. Perusing this list, you'll see that SHELL63 (4-node elastic shell) is a basic shell element and a possible candidate for our problem. A close relative is SHELL93(8node elastic shell) which has mid-side nodes in addition to the corner nodes. Since the mid-side nodes give greater accuracy, we'll use SHELL93 for our problem. Click on SHELL93in the help and take a few minutes to persue the manual page for this element. What are the "real constants" that we'll need to enter in the next step? Note that each node has six degrees of freedom: three translational and three rotational. Main Menu > Preprocessor> Element Type > Add/Edit/Delete > Add...

Pick Shell in the left field and Elastic 8node 93 in the right field. Click OK to select this element. The SHELL93 element will now be available in the meshing step. Close the Element Types menu.

## **Specify Element Constants**

## Main Menu > Preprocessor> Real Constants > Add/Edit/Delete > Add

This brings up the Element Type for Real Constants menu. Click OK to specify the real constants for the SHELL93 element.

When meshing, we'll have to assign three different thickness values: H1 for the plate; W2 and W3 for the stiffeners in the x and y directions, respectively. This means we'll have to create three real constant sets, one for each of these thickness values. According to the SHELL93 help page, if the element has a constant thickness, only TK(I), the shell thickness at the first corner node, needs to be input.

Create the first real constant set: make sure Real Constant Set No. is set to 1. For TK(I), enter H1. Leave the other fields blank since they are not applicable to our problem. Click Apply.

Create the second set: For Real Constant Set No., enter 2. For TK(I), enter {W2} and click Apply.

Create the last set: For Real Constant Set No., enter 3. For TK(I), enter W3 and click OK.

### Save: Toolbar > SAVE\_DB

Go to Step 3: Specify material properties

See and rate the complete Learning Module

Go to all ANSYS Learning Modules

- **Problem Specification**
- 1. Start-up and preliminary set-up
- 2. Specify element type and constants
- 3. Specify material properties
- 4. Specify geometry
- 5. Mesh geometry
- 6. Specify boundary conditions
- 7. Solve!
- 8. Postprocess the results
- 9. Validate the results

Step 3: Specify material properties

## Main Menu > Preprocessor > Material Props > Material Models

In the Define Material Model Behavior menu, double-click on Structural, Linear, Elastic, and Isotropic.

Enter Young's modulus **EX** in MPa: 7.3e4

Enter Poisson's Ratio PRXY:0.33. Click OK.

Close the Define Material Model Behavior menu.

Save your work: Toolbar > SAVE\_DB

Go to Step 4: Specify geometry

See and rate the complete Learning Module

Go to all ANSYS Learning Modules

**Problem Specification** 

- 1. Start-up and preliminary set-up
- 2. Specify element type and constants
- 3. Specify material properties
- 4. Specify geometry
- 5. Mesh geometry6. Specify boundary conditions
- 7. Solve!
- 8. Postprocess the results

## Step 4: Specify geometry

## **Strategy for Geometry Creation**

The geometry of the structure has a repetitive pattern as can be seen in the schematic below. We'll exploit this feature in creating the finite-element mesh for the entire structure. In this step, we'll create the geometry for the sub-section *AEFG* only. In Step 5, we'll mesh this sub-section and use it to generate the mesh for the entire structure in two steps:

- 1. We'll copy parts of AEFG to create the sub-section ABCD. (When we copy areas, the associated mesh is also copied.)
- 2. We'll copy sub-section ABCD in both directions to generate the mesh for the entire structure. Clever move, eh?



In sub-section AEFG above, the stiffeners cross each other at *F*. Modeling this correctly is tricky, so indulge me while I explain how we are going to proceed. At the end of the geometry step, the isometric view of AEFG will look as below, with the keypoint and area numbers turned on (different colors refer to different areas). If the stiffeners share keypoints 3,5 and 9, the stiffener crossing is modeled correctly and a load applied to one stiffener will be transferred appropriately to the other one. To this end, we will divide the horizontal stiffener into two areas (A3, A4). This will also yield a regular mesh as we'll see in the meshing step.



Note that the horizontal stiffener has to be split into two areas A3 and A4 because it has a larger width than the vertical stiffener. Instead, if the vertical stiffener is the wider one, it'd be the one that you'd have to split into two areas. This would change the topology of the model; something to keep in mind when you vary the stiffener dimensions in optimization studies.

## **Keypoints Coordinates**

Using the figure in the problem specification and the one above, create a table of the keypoint coordinates required to create areas A1-A4, using the param eters defined in Step 1. Recall that areas correspond to the mid-surface of the structure. Are my keypoint coordinates below correct? || No. || x || y || z ||

1	0	0	0
2	W1/ (2*NSX)	0	0
3	W1/ (2*NSX)	L1/ (2*NSY)	0
4	0	L1/ (2*NSY)	0
5	W1/ (2*NSX)	L1/ (2*NSY)	H 2
6	W1/ (2*NSX)	0	H 2
7	0	L1/ (2*NSY)	H 2
8	0	L1/ (2*NSY)	H 3
9	W1/ (2*NSX)	L1/ (2*NSY)	H 3

**Create Keypoints and Areas** 

In previous tutorials, we have defined keypoints (i.e. vertices) using menus. Here, we will instead use the command line to create keypoints. The two methods are equivalent but the latter is faster for more experienced users. Let's check the documentation to find the command for creating keypoints. In the ANSYS documentation window, select the **Search** tab, enter "keypoint" as the search term and click on **List Topics**. Double-click on 5.2 Creating Your ...\_in the left pane. Section 5.2 has useful information on creating your solid model. Scroll down to section 5.2.1. The table near the beginning of this section indicates that the command for creating keypoints is **K**\_. Note that the corresponding menu path is what we have used in previous tutorials to create keypoints. The menu path also indicates that this command is part of the Preprocessor module. Click on **K** to see the format of this command.

Since it is useful to track the keypoint and area numbers as we create the geometry, turn on keypoint and area numbering: Utility Menu > PlotCtrls > Numbering

Turn on Keypoint numbers and Area numbers and click OK.

To access the *K* command, make sure the preprocessor module is open.

Create keypoint #1 at (0,0,0): at the command prompt, type K, 1, 0, 0, 0 as below and hit *Enter*. Note that when you type the command, the format of the command pops-up as a reminder.

\Lambda ANSYS University Advanced Utility Menu (sł						
<u>F</u> ile	<u>S</u> elect	List	<u>P</u> lot	Plot	<u>C</u> trk	K, NPT, X, Y, Z
	<b>2</b>	<b>B</b>	3	?	₩	k,1,0,0,0

Similarly, create keypoints #2-#4 in the above table by entering the following at the command prompt:

K,2,W1/(2*NSX),0,0
K,3,W1/(2*NSX),L1/(2*NSY),C
K,4,0,L1/(2*NSY),0

ANSYS uses the *current* value of the parameters *W*1, L1, *NSX* and *NSY* when creating the keypoints. If you change the value of any of these parameters *a fter* you have created the keypoints, these keypoints will *not*be moved accordingly, i.e. the keypoint coordinates will still contain the old values of the parameters. It is important to remember this idiosyncracy of ANSYS; otherwise, it could come back to bite you in uncomfortable parts of your anatomy.

Is it safe to presume that you are cheating like I would and cutting-and-pasting the command line inputs? That's OK as long as you do them one-by-one so that you can track the effect of each command. To fit all the keypoints in your current view, click on the *Fit View* icon in the rightmost part of the GUI (see snapshot below). You'll have to click on this button periodically to fit the entire geometry into your view.



To create an area from keypoints #1-#4, enter a, 1, 2, 3, 4 at the command line. Note that ANSYS automatically assigns the label A1 to this first area. This area corresponds to the plate.

Next create keypoints #5 and #6 followed by the area corresponding to the stiffener in the y-direction. Enter

K,5,W1/(2\*NSX),L1/(2\*NSY),H2
K,6,W1/(2\*NSX),0,H2
A,2,3,5,6

To bring up the isometric view, click on the *Isometric View* icon in the right part of the GUI (see snapshot below). The area is labeled A2. If the area disappears from the view, select Utility Menu > Plot > Areas.



Now that we have gotten the hang of this business, we can create the remaining keypoints and areas in our sleep (remember to wipe the drool off the keyboard):

K,7,0,L1/(2\*NSY),H2 K,8,0,L1/(2\*NSY),H3 K,9,W1/(2\*NSX),L1/(2\*NSY),H3 A,3,4,7,5 A,5,7,8,9 Utility Menu > Plot > Areas

The geometry should look like this:



Save your work: Toolbar > SAVE\_DB

Go to Step 5: Mesh geometry

See and rate the complete Learning Module

Go to all ANSYS Learning Modules

- Problem Specification
- 1. Start-up and preliminary set-up
- Specify element type and constants
   Specify material properties
- 4. Specify geometry
- 5. Mesh geometry6. Specify boundary conditions
- 7. Solve!
- 8. Postprocess the results
- 9. Validate the results

## Step 5: Mesh geometry

As discussed in the previous step, we'll first mesh the subsection AEFG that we just created.

### Set Mesh Size Along Edges

We'll use the previously-defined parameters NDIV\_X, NDIV\_Y and SIZE\_Z to set the mesh size along edges. The table below describes what each parameter is and the value we have assigned to it.

Parameter	Value	Description	
NDIV_X	3	No. of divisions for edges along $x$	
NDIV_Y	6	No. of divisions for edges along y	
SIZE_Z	5	Size of divisions for edges along z	

Edges along *z* are of two different lengths, as should be apparent from the geometry display. For instance, the edge between keypoints #5 and #9 is smaller than that between keypoints #3 and #5. By setting the element size rather than the number of divisions, we can use the same parameter for both edge lengths.

#### Bring up the *MeshTool*: Main Menu > Preprocessor > MeshTool

We are going to continually use the MeshTool to generate the mesh. So resize and rearrange the windows slightly so that you can access the MeshTool, ANSYS GUI, and tutorial simultaneously.

If you have trouble selecting the correct line below, **hold down** the left mouse button until the line is selected and then release the left button. If you want to **deselect** a line, right-click to go into deselect mode, left-click on the line to be deselected and right-click again to go back into select mode.

Under Size Controls and Lines, click Set. Pick all four lines in the x-\_direction. and click OK in the pick menu. Enter NDIV\_X for No. of element divisions and click Apply.

Next, pick all three lines in the y-direction and click OK in the pick menu. Enter NDIV\_Y for No. of element divisions and click Apply.

Last, pick all five lines in the z-direction and click OK in the pick menu. Enter SIZE\_Z for *Element edge length*. Make sure *No. of element divisions* is blank. Click *OK*.

Plot lines to see the element divisions along edges and check that they have been set correctly: **Utility Menu > Plot > Lines**. If you made an error, repeat the above steps before saving.



## **Generate Mesh for Plate**

Recall that the plate and the horizontal and vertical stiffeners have different thicknesses which have been assigned to different "real constant" sets. Jog your memory about which thicknesses have been assigned to which "real constant" sets in Step 2.

We'll first mesh the plate using real constant set #1. Under *Element Attributes* in *MeshTool*, click on *Set*. You will see that the element type and material number are already set and the default real constant set is #1. These are the options we need for the plate; so these don't need to be changed. Click *Canc el.* 

Plot areas: Utility Menu > Plot > Areas

Click on Mesh in MeshTool. Pick area A1 and click OK. The resulting mesh for the plate is displayed.

## **Generate Mesh for Vertical Stiffener**

Under Element Attributes in MeshTool, click on Set. Set Real constant set number to 2 and click OK.

Plot areas: Utility Menu > Plot > Areas

Click on Mesh in MeshTool. Pick area A2 and click OK. The resulting mesh for the plate is displayed.

#### **Generate Mesh for Horizontal Stiffener**

Under Element Attributes, click on Set. Set Real constant set number to 3 and click OK.

Plot areas: Utility Menu > Plot > Areas

Click on Mesh in MeshTool. Pick areas A3 and A4 and click OK.



Let's change the graphical display so that the geometry is displayed as a solid model with the shell thicknesses shown. At the command prompt, type /esh ape, 1 and then select Utility Menu > Plot > Replot. When the */ESHAPE* command in issued, ANSYS uses the real constants associated with each element to determine its shape. (Note that commands are not case-senstive.)



Do the relative thicknesses of different parts of the shell look correct? Feel free to manipulate the graphical display to check this.

You can access different model views such as front, right, isometric etc. using the buttons to the right of the graphics window. At the bottom of this row

of icons is the *Dynamic Model Mode*. Clicking this icon allows you to manipulate the model using the mouse (alternatively, you can hold down the *Ctrl* key). To see the help page on this mode, right-click on the icon and select *Dialog Overview > Pan, Zoom, Rotate > Dynamic Mode: Model.* 

Save: Toolbar > SAVE\_DB

### **Copy Mesh in x-Direction**

Turn off the element shapes to make the display less cluttered by entering the following commands:

/eshape,0 /replot

Plot areas: Utility Menu > Plot > Areas

Copy areas: Main Menu > Preprocessor > Modeling > Copy > Areas Pick A1, A3, and A4 and click *OK*. (Hold down the left mouse button until the correct area is selected.)

Copy Areas menu: We want two copies including the original, so leave Number of copies as 2. For X-offset, enter W1/ (2\*NSX), leave Y- and Z-offsets blank and click OK.

Since the associated keypoints are also copied over, you'll notice that there is a collection of two coincident but separate keypoints along shared boundaries where the original and copied entities overlap. It's key that we [merge these coincident keypoints|SIMULATION:Semi-monocoque shell page 5]; we'll undertake this after we are finished with the copy step.

Have the elements associated with the areas also been copied? Check this: Utility Menu > Plot > Elements



### Save: Toolbar > SAVE\_DB

As with keypoints (and lines too), there is a collection of two coincident but separate nodes along the shared boundaries. Let's convince ourselves of this truism:

- Turn on node numbers (in addition to keypoint and area numbers) using Utility Menu > PlotCtrls > Numbering
- Display elements and nodes together: Utility Menu > PlotCtrls > Multi-Plot Ctrls > OK. Leave only Nodes and Elements turned on and click OK.
   Select Utility Menu > Plot > Multi-Plots.
- Zoom into the bottom-center of the model as in the snaphsot below. At the bottom of the symmetry plane, you should notice that there are actually two nodes, 2 and 172. Node 2 is associated with the original area and node 172 with the copy. We'll merge coincident nodes a little later. (Note that your node numbers may be different from mine since numbering can vary on different computer systems.)



## **Copy Mesh in y-Direction**

Plot areas: Utility Menu > Plot > Areas

Click on the Fit View and Isometric View icons in the rightmost part of the GUI.

Copy areas: Main Menu > Preprocessor > Modeling > Copy > Areas

Pick A1, A2, and A5 and click OK.

Copy Areas menu: Leave Number of copies as 2. For Y-offset, enter L1/ (2\*NSY); delete X-offset; leave Z-offset blank and click OK.

Check the resulting mesh for sub-section ABCD: Utility Menu > Plot > Elements

Turn-off node numbers to reduce clutter.



## Copy Sub-Section ABCD

How many copies of sub-section ABCD do we need to make in the x- and y-directions? What are the values of X-Offset and Y-Offset in each case? Jot your answers down so that you can check the values below.

Copy areas: Main Menu > Preprocessor > Modeling > Copy > Areas > Pick All

Copy Areas menu: Number of copies = NSX; X-offset = W1/NSX; Y- and Z-offsets should be blank or zero. Click Apply.

Repeat copy in y-direction: Select Pick All again in the pick menu.

Copy Areas menu: Number of copies = NSY; Y-offset = L1/NSY; X- and Z-offsets should be blank or zero. Click OK.

Check the resulting mesh: Utility Menu > Plot > Elements



## **Merge Coincident Entities**

We saw earlier that the copy operations resulted in coincident nodes, keypoints, etc. along shared boundaries. We need to merge these coincident items so that separate portions of the model are combined into one. Otherwise, the various portions will live as independent entities and loads applied to one portion will not be transferred to its neighbors. The effect of the merge operation is shown schematically below.



View documentation about the merge utility: ANSYS Help > Contents > Modeling and Meshing Guide > Number Control and Element Reordering > Number Control

This section has useful information about merging entities. It indicates that one can either merge keypoints, nodes, etc. individually or merge *all*coincident entities at once (with ANSYS ensuring that they are merged in the proper sequence). Since we'd like to palm off as much work as possible to ANSYS, we'll use the latter option.

#### Select Main Menu> Preprocessor> Numbering Ctrls> Merge Items

For Type of item to be merged, select All and click OK. This will merge all coincident entities.

Earlier we saw that nodes 2 and 172 were coincident. Zoom in on this region again with node numbers turned on. What do you see?



If you performed the merge operation correctly, you'll see that the higher numbered node has been deleted and the two coincident nodes have been replaced by a single node.

#### Save: Toolbar > SAVE\_DB

### **Compress Item Numbers**

If you scroll down the help section on numbering that we've been peeking at, you'll find a useful spiel on *Compressing Item Numbers*(section 11.1.2): "As you build your model, you might, by deleting, clearing, merging, or performing other operations, create unused slots in the numbering sequence for various items. These slots will remain empty for some items (such as elements) but will be filled in for other items (such as keypoints) as new items are created. To save data storage space (by eliminating otherwise empty numbers) or to preserve desired sequencing (by forcing newly-created items to be assigned numbers greater than those of existing items), you can eliminate these gaps by "compressing" your numbering".

Check the range of node numbers before compressing the numbering: Utility Menu > List > Nodes > OK

Compress numbering for all items (nodes, elements, etc.): Main Menu> Preprocessor> Numbering Ctrls> Compress Numbers

For Item to be compressed, select All and click OK.

Re-check the range of node numbers after compressing. You should find that the range of node numbers is reduced since there are now no gaps in the numbering.

Close MeshTool.

Save: Toolbar > SAVE\_DB

Go to Step 6: Specify boundary conditions

See and rate the complete Learning Module

Go to all ANSYS Learning Modules

- **Problem Specification**
- 1. Start-up and preliminary set-up
- 2. Specify element type and constants
- 3. Specify material properties
- 4. Specify geometry
- 5. Mesh geometry
- 6. Specify boundary conditions
- 7. Solve!
- 8. Postprocess the results
- 9. Validate the results

## Step 6: Specify boundary conditions

The boundary conditions given in the problem specification are summarized in the schematic below. Keep in mind that the edge conditions need to be applied to the plate as well as the stiffeners.



## Apply Symmetry along AH

We'll apply this BC in two steps:

- 1. Select edges along AH
- 2. Apply symmetry condition to the selected edges

#### Plot areas: Utility Menu > Plot > Areas

Adjust the display: Click on the Isometric View and Fit View icons in the rightmost part of the GUI.

Utility Menu > PlotCtrls > Numbering: Turn off area and node numbering; turn on line numbering.

### Select all edges along AH: Utility Menu > Select > Entities

We are going to continually use the Select Entitiesmenu to apply the BC's. So resize and rearrange the windows slightly so that you can access this menu, the ANSYS GUI, and the tutorial simultaneously.

Select Entities menu: Select Lines from the pull-down menu at the top. Select below that. Choose **By LocationY coordinates**. Under **Min,Max**, enter 0. This will select all lines whose **centers** lie at *y*=0. Make sure **From Full** is selected so that we are selecting entities from the *full* model. Click **Apply**.



Check which lines have been selected: Select Entities menu >Plot. You should see that the edges along AH have been selected.



Apply symmetry condition to the selected edges: Main Menu > Preprocessor > Loads > Define Loads > Apply > Structural > Displacement > Symmetry B.C. > On Lines > Pick All

This applies the symmetry condition to all the selected lines.

Select the entire model: Click Select All and then Replot in the Select Entities menu. You should see the S symbol along the edges where the symmetry BC has been applied.

## Apply Symmetry along AJ

We'll first select all edges along AJ. Go back to Select Entities menu: Leave Lines and By Location in place. Choose X coordinates. Under Min,Max, retain 0. This will select all lines whose centers lie at x=0. Make sure From Full is selected. Click Apply.

Check which lines have been selected: Select Entities menu > Replot. You should see that only the edges along AJ are currently selected.

Let's apply the symmety BC to these edges: Main Menu > Preprocessor > Loads > Define Loads > Apply > Structural > Displacement > Symmetry B. C. > On Lines > Pick All

Select the entire model: Click Select All and then Replot in the Select Entities menu.

## Apply Clamped BC along HI

Now that we've gotten the hang of this boundary business, let's mop up Operation BC's in short order.

Select Entities menu: Leave Lines, By Location and X coordinates selections in place. Under Min, Max, enter W1. This will select all lines whose centers lie at x=W1. Make sure From Full is selected. Click Apply.

Select Entities menu > Replot

Constrain all six nodal degrees of freedom (DOF) for the selected edges: Main Menu > Preprocessor > Loads > Define Loads > Apply > Structural > Displacement > On Lines > Pick All > All DOF > OK

The (cluttered) display will show that all six DOF's have been constrained.



#### Select Entities menu: Select All and Replot

## Apply Clamped BC along JI

Select Entities menu: Leave Lines, and By Location in place. Choose Y coordinates. Under Min, Max, enter L1. This will select all lines whose centers lie at y=L1. Make sure From Full is selected. Click Apply.

Select Entities menu > Replot

Constrain all six nodal degrees of freedom (DOF) for selected edges: Main Menu > Preprocessor > Loads > Define Loads > Apply > Structural > Displacement > On Lines > Pick All > All DOF > OK

Select Entities menu: Select All and Replot

Save: Toolbar > SAVE\_DB

## **Apply Pressure on Plate**

Utility Menu > PlotCtrls > Numbering: Turn off line numbering.

#### Utility Menu > Plot > Areas

Choose areas corresponding to the plate: In the *Select Entities* menu, select *Areas* from the pull-down menu at the top. Leave *By Location* below that. Choose *Z coordinates* Under *Min,Max*, enter 0. This will select all areas whose centers lie at *z*=0. Make sure *From Full* is selected. Click *Apply*.

Check which areas are currently selected: Select Entities menu > Replot

Apply a pressure of 0.05 N/mm<sup>2</sup> on the plate in the +z direction: Main Menu > Preprocessor > Loads > Define Loads > Apply > Structural > Pressure > On Areas > Pick All

For VALUE, enter 0.05. Click OK.

ANSYS will mark the faces where the pressure is applied. Let's instead plot the applied pressure using arrows to check its direction: Utility Menu > PlotCtrls > Symbols. For Surface Load Symbols, select Pressures and under Show pres and convect as, select Arrows. Click OK. Are the pressures acting in the right direction?

Select Entities menu: Select All, Replot and Cancel. You should now see the entire model. Review that all the BC's have been applied correctly.



#### Save: Toolbar > SAVE\_DB

## **Create Log File**

In parametric studies to be undertaken later, we'll start with the log file containing the commands from the first six steps that we just went through. To save this log file, select

### Utility Menu > File > Write DB log file

Under *Write Database Log* to, enter the filename for the logfile: *shell\_step6.lgw*. At the bottom of this menu, select *Write Essential Commands* only. Click *OK*. Review *shell\_step6.lgw* by opening it in a text editor.



#### Go to Step 7: Solve!

#### See and rate the complete Learning Module

Go to all ANSYS Learning Modules

## Problem Specification

- 1. Start-up and preliminary set-up
- 2. Specify element type and constants
- 3. Specify material properties
- 4. Specify geometry
- 5. Mesh geometry
- 6. Specify boundary conditions
- 7. Solve!
- 8. Postprocess the results
- 9. Validate the results

## Step 7: Solve!

#### Enter Solution Module: Main Menu > Solution

Enter check in the *Input*window. If the problem has been set up correctly, there will be no errors or warnings reported. You should see the following message in the *Output* window: The analysis data was checked and no warnings or errors were found.

#### Main Menu > Solution > Solve > Current LS

Review the information in the /STATUS Command window. Close this window.

Click OK in Solve Current Load Step menu.

ANSYS performs the solution and a window should pop up saying "Solution is done!". Close this window.

Save: Toolbar > SAVE\_DB

Go to Step 8: Postprocess the results

See and rate the complete Learning Module

Go to all ANSYS Learning Modules

- Problem Specification
- 1. Start-up and preliminary set-up
- 2. Specify element type and constants
- 3. Specify material properties
- 4. Specify geometry
- 5. Mesh geometry
- 6. Specify boundary conditions
- 7. Solve!
- 8. Postprocess the results
- 9. Validate the results

## Step 8: Postprocess the results

## **Plot Deformed Shape**

The Results Viewer provides a convenient way to review results.

## Main Menu > General Postproc > Results Viewer

The title bar for the *Results Viewer* indicates that the results are being read from the *shell.rst* file. Rearrange the windows slightly so that you can access the *Results Viewer*, ANSYS GUI and tutorial simultaneously.

#### Under Choose a result item, select Nodal Solution > DOF Solution > Displaced structure. Click on the Plot Results icon.

Hold down the *Ctrl* key and use the mouse to manipulate the model view; check that the BC's and loads have been imposed correctly. The snapshot below shows one view that is useful in checking the BC's. Are the symmetry and clamped conditions satisfied at the corresponding edges for the facesheet as well as the stiffeners? Is the model deformation as you'd expect for a uniform pressure on the facesheet in the +z direction?



The maximum displacement DMX=3.88 mm. Where do you think this occurs? We'll check this in a minute.

Animate the defromation and obsessively recheck the BC's:

#### Results Viewer > Animate Results > Deformed Shape > OK > Def + undef edge > OK

Select Forward Only in the Animation Controller.

## **Plot w Displacement**

In the *Results Viewer*, in place of *Displaced structure*, choose Nodal Solution > DOF Solution > Z-Component of displacement. Click on the *Plot Results* icon.



The location of maximum deflection  $w_{max}$  is labeled *MX*. This occurs not at the facesheet center but on the edge *x*=0, at approximately *y*=*L*1/3. As expected, the deflection is zero along the clamped edges.

To save a copy of this plot, select Results Viewer > Image Capture > Capture to file > OK.

For filename, enter w\_contours. This creates the file \_w\_contours.png\_ in your working directory. Check that you can open this file using your pet image viewer.

## **Deflection at Facesheet Center**

To query the value of the deflection at the center of the facesheet, select the Query Results icon in the Results Viewer.

Pick the node at X=0, Y=0. The coordinates of the picked node and the corresponding value of UZ (i.e. w displacement) are displayed in the Query Subgrid Results menu. The deflection at the center of the facesheet is 3.8 mm.

Cancel the Query Subgrid Results menu.

## xx for Facesheet

For clarity, let's first plot v for just the facesheet. Select the elements for the facesheet in two steps:

- 1. Select areas corresponding to the facesheet.
- 2. Select elements attached to these previously selected areas. Close the Results Viewer.

#### Utility Menu > Plot > Elements

#### Utility Menu > Select > Entities

Select Entities menu: Select Areas, By Location and Z coordinates. Under Min, Max, enter 0. Make sure From Full is selected. Click Apply.

Following this, select *Elements, Attached to, Areas* and *From Full*. Click *Apply* and then *Replot*. You should see that only elements for the facesheet are currently selected.

#### Main Menu > General Postproc > Results Viewer > Nodal Solution > Stress > X-Component of stress

#### Click Plot Results icon.

Shell theory provides the stresses through the thickness of the shell. This is illustrated in the help page for SHELL93 element. If, like me, you are looking at the top of the facesheet, then the contours values correspond to  $_{xx}$  values for the top face. Check the  $_{xx}$  value for the top face at the facesheet center:

#### **Results Viewer > Query Results**

Pick the node at X=0, Y=0. I get xx=51 MPa at the center-top of the facesheet.

Hold down the *Ctrl* key and flip the model over so that you are looking at the *bottom* of the facesheet as in the snapshot below. Now the contours values correspond to  $_{xx}$  values for the facesheet *bottom*. Use *Query Results* to determine  $_{xx}$  at the center-*bottom* of the facesheet. I get -56 MPa. What do you get? The negative sign indicates compression.



(For an enlarged view, click and maximize the browser window)

Thus, at the facesheet center, yy varies from a tensile stress of 51 MPa at the top to a compressive stress of 56 MPa at the bottom.

Using *Query Results*, I get  $xx^{=116}$  MPa at the edge point x=W1, y=0 for the bottom of the facesheet (see snapshot above). What's the value you finagled out of ANSYS?

Do these values look plausible? We'll investigate this in Step 9 when we compare the center and edge stress values to plate theory.

Cancel the Query Subgrid Results menu.

## yy for Facesheet

## Results Viewer > Nodal Solution > Stress > Y-Component of stress

Click *Plot Results* icon. The snapshot below shows the yy contours.



Using Query Results, I get the following values for the bottom of the facesheet (see snapshot above):

- 1. At the center,  $_{\gamma\gamma}$ = -28 MPa.
- 2. At the clamped edge location (x=0, y=L1),  $_{yy}$ = 77 MPa. What are your corresponding values?

## xx for Stiffeners

Currently, the facesheet is selected and the stiffeners are unselected. To plot stress contours for the stiffeners, we'll unselect the facesheet and select the stiffeners i.e. reverse the selection. This can be done using the *Invert* operation:

#### Select Entities menu> Invert

### Select Entities menu> Replot

(In MS-Windows, you can cycle through windows on the desktop by holding down the *Alt* key and repeatedly pressing the *Tab* key. In case the *Select Entities* menu has disappeared, exit the *Results Viewer*, bring up the *Select Entities* menu and re-enter the *Results Viewer*.)

### Results Viewer > Nodal Solution > Stress > X-Component of stress

#### Click Plot Results icon.

Manipulate the view so that you are looking down on the top of the stiffeners as in the snapshot below. You might have to flip the model over.



The <sub>xx</sub> values for the stiffeners in the y-direction is virtually zero; confirm this using **Query Results**. This means that, as expected, the load in the x-direction is carried by the stiffeners in that direction.

Let's determine <sub>xx</sub> values at the *top* of the x-stiffener closest to the center; we'll compare these values to plate theory in Step 9. Using **Query Results**, I get the following values at the top of this stiffener (see snapshot above):

- **1.** At (*x*=0, *y*=L<sub>1</sub>/6), <sub>*xx*</sub>= 312 MPa.
- 2. At the clamped edge location (x=W<sub>1</sub>, y=L<sub>1</sub>/6),  $xx^{=}$  -653 MPa. What are your corresponding values?

## yy for Stiffeners

### Results Viewer > Nodal Solution > Stress > Y-Component of stress

Click Plot Results icon.



The <sub>yy</sub> values for the stiffeners in the x-direction is virtually zero; confirm this using **Query Results**. This means that, as expected, the load in the y-direction is carried by the stiffeners in that direction.

Let's determine <sub>yy</sub> values at the *top* of the *y*-stiffener closest to the center which we'll compare to plate theory in Step 9. Using **Query Results**, I get the following values at the top of the stiffener (see snapshot above):

- 1. At (x=W<sub>1</sub>/4, y=0), <sub>yy</sub>= 38 MPa.
- 2. At the clamped edge location ( $x=W_1/4$ ,  $y=L_1$ ), y=-300 MPa. What are your corresponding values?

#### Save: Toolbar > SAVE\_DB

Go to Step 9:Validate the Results

See and rate the complete Learning Module

Go to all ANSYS Learning Modules

- **Problem Specification**
- 1. Start-up and preliminary set-up
- 2. Specify element type and constants
- 3. Specify material properties
- 4. Specify geometry
- 5. Mesh geometry
- 6. Specify boundary conditions
- 7. Solve!
- 8. Postprocess the results
- 9. Validate the results

## Step 9: Validate the results

We checked in the previous step that the BC's have been applied correctly and the deflection looks plausible.

### **Comparison With Plate Theory**

An FEA analyst displays his mettle by going head-to-head with theory. The theoretical solution for a clamped plate subjected to pressure is presented by Timoshenko and Woinowsky-Krieger, page 202. This solution can be modified to account for the presence of stiffeners using the parallel axis theorem. This calculation and the resulting stress and displacement values have been generously provided by Prof. Alan Zehnder and are sumarized in this pdf document. Do take the time to review this document.

The head-to-head comparison of the analytical values with the FEA values from Step 8 at the center of the structure is presented in the following table.

Entity	Location	FEA	Theory
w		3.8 mm	3.6 mm
xx	Bottom	-56 MPa	-50 MPa
xx	Тор	312 MPa	350 MPa
уу	Bottom	-28 MPa	-20 MPa
уу	Тор	38 MPa	105 MPa

The deflection at the center is about 8% larger than the theoretical value due to shear deformation in the FEA model that is not accounted for in the analytical result. Correlation of stresses in the center is reasonably good. It might improve if solution for anisotropic plate were used. Also, the stiffeners are not at the centerline of the model, while maximum stresses in theory are calculated at the center.

The head-to-head comparison of the edge stresses is given in the following table.

Entity	Location	FEA	Theory
xx	Bottom	116 MPa	100 MPa
xx	Тор	-653 MPa	-704 MPa
уу	Bottom	77 MPa	78 MPa
уу	Тор	-300 MPa	-403 MPa

There is good correlation of the edge stress on the bottom of facesheet but the edge stress at the top of the stiffeners is overestimated by the theory. This is possibly due to the stiffeners not being at the centerline of the model while the maximum stresses in theory are calculated at the center.

Back to Problem Specification

See and rate the complete Learning Module

Go to all ANSYS Learning Modules