2D Steady Conduction - Numerical Results

Author: Rajesh Bhaskaran, Cornell University

Problem Specification

- 1. Pre-Analysis
- 2. Geometry
- 3. Mesh
- 4. Model Setup
- 5. Numerical Solution
- 6. Numerical Results
- 7. Verification & Validation

Exercises

Comments



Temperature Contours

Check your Understanding

Consider the following steps:

- 1. Invert the stiffness matrix to determine the nodal temperature values.
- 2. Plot the temperature contours using nodal temperature values.

Steps 1 and 2 take the same amount of time.

Step 1 takes a longer time than step 2.

Step 1 takes a shorter time than step 2.

(To see the answer, go to the 2D Conduction section of Module 1 in our free online course on ANSYS simulations. You need to sign in to edX.org to access the course.)

Heat Flux Vectors

Probe Temperature

Temperature Along a Line

Go to Step 7: Verification & Validation

Go to all ANSYS Learning Modules