

Community Agreements

1. When you leave a layup or paint booth project: **Leave a note!**

- Write: 1) team name, 2) your name, 3) phone, 4) end time
- Specify whether other teams can move project / unplug the pump once time is up

2. When you cut carbon fiber:

- Wear particulate masks, eyeglasses, and gloves!!
- Let other people around you know they should wear masks
- Mist spray the composite material (use squirt bottles)
- Cut on downdraft table
- Point a vacuum at cut area during entire time (one person holds vacuum, one person cuts)

3. Masks are good for **8 hours** of chemical contact and should **only be reused if you are taking a 1 hour break or less.**

4. **Do not drink or eat food in composites.** Hazardous chemicals are in use here. Step out to the hallway or office for breaks.

5. Be mindful that **people need acrylic top tables for layups.** Use wooden tables if you aren't doing a layup.

6. **Pick up after yourself.** Do not leave scraps or trash on the floor.

7. **Clean off tables when you are done.** Use acetone as necessary.

8. **Dispose of any applicable chemical waste in the chemical waste bin.** Fuel and oils (autolab waste) is NOT allowed in the bin. Clean off tools using acetone into the bin, NOT into the sink.

9. Train your team members well.